



Accurate information you can rely on.

Light-Gauge Steel Inspection Report

Client:	Town of Colchester	Project No.:	5836
Project:	Colchester Senior Center	Report No.:	086
Inspector:	Randy Zajac AWS CWI 02070541	Date:	1/15/2024
Subject:	Field Verification Inspection	Page:	1 of 2

A field inspection was performed at the above-referenced project today. The purpose of this inspection was to verify that completed work was performed utilizing the engineer-approved drawings, the project specifications, and the manufacturer's-approved erection drawings.

The IMTL representative was on-site at the Colchester Senior Center project as scheduled by the Superintendent Mr. Robert Lamarre of BRD Builders, the general contractor for the project.

The scope of the visit was to perform a final inspection of exterior/shear wall cold formed framing Grid Area 1-11/A-V.

GDS is responsible for the on-site erection of structural steel for the project.

The writer referenced the approved shop drawings and the previous reports in order to perform the inspection.

It was viewed by the writer that all details have now been erected and fastened per the shop drawings. The field erection of cold formed walls at the referenced area is acceptable.

This inspection was reviewed with the Superintendent and erector at its conclusion.



pc: Tony Tarnowski, Town of Colchester / Scott Errison, E2 Engineers / Mark Garilli, Jonathan Gombotz, Michael Jackson, CS Group / Chris Nardi, Bob Washburn, Silver Petrucelli / Rob Lamarre, Ryan Clifford, BRD Builders

jd

**Steel - Outstanding Non-Conformities
Structural Steel & Welding, Light-Gauge Steel**

Report No. 086
Page 2 of 2

No new discrepancy inspection dates:
 8/10/23 9/26/23 UT
 9/11/23 12/22/23
 9/19/23
 9/22/23

Steel Inspector:
Randy Zajac

PROJECT: Colchester Senior Center		S	Date Inspected & Rejected	Date of Rework	Date Accepted	Awaiting Engineer's Decision	Report No.	Item No.	Comments
Location or Piecemark:		F-LG F-SS							
Exterior Framing Grid Area		F-LG	12/5/23		1/15/24		083/086	1	Shots not fully engaged into concrete
Exterior Framing Grid Area		F-LG	12/12/23		1/15/24		084/086	2	Shot not fully engaged into concrete
6-13/A-V									

S: Shop, F: Field, SS: Structural Steel, LG: Light-gauge
 This same form to accumulate throughout all steel inspections for this project and a copy forwarded to each steel inspector for continuous tracking of items.